

18706 North Creek Parkway Suite 110, Bothell, Washington 98011

Drill Method: Geoprobe

Drill Date: 10/15/01

Project: Schwerin Concave

Log of Borehole: TB-I

Location: Walla Walla, WA

Project No.: 01-0817-00-2124-400

Logged by: Andy Keim

Sheet: 1 of 1

Client: Washington Department of Ecology Ecology PM: Bill Fees

SUBSURFACE PROFILE					SAMPLE			
feet (bgs)	feet (MSL)	Symbol	Description	Number	Type	N-Value	Recovery	Well Completion Details
0-	0.0	1111111111	Ground Surface				e e	
2	0.0	AND THE PROPERTY OF THE PROPER	SILT, ML, with some leaves (organics) in the top 4" below ground surface, medium gray brown, slightly moist, becomes slightly reddish brown with mottling in bottom 6" at 3' to 3.5' bgs. Silt becomes slightly moist and "compressed" stiff at	01	, garage and a second		2'	
6 88			4' bgs. Light brown interval 4" thick at 6.5' bgs with flour texture and increased clay content with depth to 10' bgs, moist, clayey Silt from 10- 11' bgs.	02			2 5'	
10				03			2.5'	
12	-11.0 11.0 -12.0 12.0 -13.0		Clayey GRAVEL, GC-GM, with ironoxide staining, some unsaturated zones in gravel layer, gravels sub rounded.					
14-	13.0		Silty SAND, SM. Silty GRAVEL, with some clay, GM-GC, iron-oxide staining with	04			27"	
16			alternating dry and slightly moist interbedded clayey silt layers.					
18	-18.0 18.0		Refusal at 18' bgs					
Drilled By: Environmental West Exploration Hole Size:								